

# PSI-X-3PMETER-HY-TA

PSI-X Three-Phase Meter (with CTs)



## External current transformer

Three 200/5 A CTs  
included in the package

## Electrical Characteristics

Application	Three phase
Nominal voltage	3 x 220/380 V ~ 3 x 240/415 V
Operating range	0,7 - 1,3 V
Rated input current	5 A <sup>(1)</sup>
Frequency	50 / 60 Hz
Power consumption	≤ 1,5W

1. It is necessary to provide current transformers (CTs) with an appropriate transformation ratio (200/5 A CTs included in the package)

## General information

Brand	CHINT
Model	DTSU666-CT
Display	LCD
Communication	RS485
Operating temperature range	-25 °C ~ 75 °C
Relative humidity	<75% without condensation
Ingress protection	IP51
Mounting system	Support Bracket DIN35
Dimensions (H x W x D)	100 x 72 x 65 mm
Weight	0,4 kg
Compatible CT	3 x LCTA97C2 200/5 A 1 VA

## Certifications

For a complete list of certificates, please refer to [www.peimar.com](http://www.peimar.com)